## October 2016 - PRELIMINARY

## Riser Replacement Calendar - '01 Mst Baths/'02 Baths 3rd to 29th Floors

Sunday Monday Tuesday Wednesday Thursday Friday

Demo - Anticipated start date - demolition and preparations

Plumb - riser and branchline replacements

Ins - insulation and fire-stopping Recon - major reconstruction Punchlist - miscellaneous items Calendar indentifies dates we expect to begin work, and indicates what types of work we anticipate being started or in progress.

Saturday

2	3	4	5	_	= 1	
	Demo 3-5	Daily Water	Demo 9-11	Demo 12-15	Demo 16-18	
		Shut Offs Begin	Plumb 5-6	Plumb 7-8	Plumb 9-10	
		Demo 6-8		Ins 3-5	Ins 6-8	
9	10	Plumb 3-4	40	10	4.4	
9	10 Demo 19-21	11 Demo 22-24	12 Demo 25-27	13 Demo 28-29	14 Plumb 20-21	
	Plumb 11-12	Plumb 14-15	Plumb 16-17	Plumb 18-19	Ins 17-19	
	Recon 3-6	Recon 3-6	Ins 9-11	Ins 12-15	Recon 5-8	
	Board Meeting 7:30	Kecon 5-0	Recon 3-6	Recon 3-6	Wtr Shut Offs End	
16	The state of the s	18	19			
10	Plumb 22-23	Plumb 24-25	Plumb 26-27	Plumb 28-29	Ins 26-29	
	Recon 5-8	Recon 7-10	Ins 20-22	Ins 23-25	Recon 9-12	
	1100011 3-0	Recon 7-10	Recon 7-10	Recon 9-12	1100011 3-12	
			1000117 10	11000113 12		
23		25	26		28	
	Recon 11-15	Recon 11-15	Recon 14-17	Recon 14-17	Recon 16-19	
	Board Meeting 7:30					
30	31					
	Recon 16-19					
	-					Page 1 of 2

Riser Replacement Calendar - '01 Sunday Monday Calendar identifies dates we expect to begin work, and indicates what types of work we anticipate being started or in progress.		Tuesday	Wednesday	Thursday	Friday	Saturday
		1 Recon 18-21	Recon 18-21	2 3 Recon 20-23	4 Recon 20-23	5
6	7 Recon 22-25	8 Recon 22-25	Recon 24-27	9 10 Recon 24-27	11 Recon 26-29	12
13	14 Recon 26-29 Board Meeting 7:30	15 Recon 28-29	Recon 28-29	6 17 Punchlist	18 Punchlist	19
20	21 Punchlist	22 Punchlist	2 23 Punchlist	3 24 Thanksgiving	25	26
			Office Closes 3pm		Office Hrs 9am-3pm	<u> </u>
27	Punchlist Board Meeting 7:30	29 Punchlist	9 30 Punchlist	Demo - demolition an Plumb - riser and brai Ins - insulation and fir Recon - major recons Punchlist - miscellane	nchline replacements re-stopping struction expected	